

INTERNAL TESTS

Ryno® Adirondack

Sample: Ryno Adirondack chair
Date: 14/08/2026
Tester #1: Lizzie Waters
Standard: PIN-001.2:2025



Test Type	Photos	Comments (including pass/fail)
Static load		A load of 264kg was applied to the chair during testing. Throughout the test, the chair remained stable with no visible signs of deformation, structural damage, or loss of function. Following removal of the load, the chair maintained its original form and stability. Result: PASS
Static load		A load of 418kg was applied to the chair during testing. Throughout the test, the chair remained stable with no visible signs of deformation, structural damage, or loss of function. Following removal of the load, the chair maintained its original form and stability. Result: PASS

Summary:
The chair successfully supported the applied load and remained stable throughout the test, with no visible signs of deformation or structural issues.

Result: PASS